
Appendix K


I-40 Conceptual Alternatives


NMDOT


MEXICO DEPARTMENT : TRANSPORTATION


NEW N
































































SEE INTERCHANGE LAYOUTS


NOTE: SEE APPENDIX A, HIGHWAY OPERATIONAL PLAN FOR PROPOSED ITS AND AND DRAINAGE RECOMMENDATIONS















































- (PROPOSED CORRECTION W/ FULL RECONSTRUCTION)
- VERTICAL CURVE DOES NOT MEET CURRENT AASHTO DESIGN GUIDELINE (PROPOSED CORRECTION W/ FULL RECONSTRUCTION)
- 4 BRIDGE POOR CONDITION


NOTE: SEE APPENDIX A, HIGHWAY OPERATIONAL PLAN FOR PROPOSED ITS AND AND DRAINAGE RECOMMENDATIONS


CN 6101580 PHASE B STUDY CONCEPTUAL ALTERNATIVES




























































































































































































































































































NMDOT

MEXICO DEPARTMENT = TRANSPORTATION

NEW N





- 1 HORIZONTAL CURVE DOES NOT MEET CURRENT
 AASHTO DESIGN GUIDELINE
 (PROPOSED CORRECTION
 W/ MILL & INLAY)
- (2) HORIZONTAL CURVE DOES NOT MEET CURRENT
 AASHTO DESIGN GUIDELINE
 (PROPOSED CORRECTION
 W/ FULL RECONSTRUCTION)
- 3 VERTICAL CURVE DOES NOT MEET CURRENT AASHTO DESIGN GUIDELINE (PROPOSED CORRECTION W/ FULL RECONSTRUCTION)
- 4 BRIDGE POOR CONDITION

NOTE: SEE APPENDIX A, HIGHWAY OPERATIONAL PLAN FOR PROPOSED ITS AND AND DRAINAGE RECOMMENDATIONS.

PRELIMINARY RUCTION FROM FOR CONSTRUCTION

CN 6101580 PHASE B STUDY CONCEPTUAL ALTERNATIVES

NMDOT

MEXICO DEPARTMENT - TRANSPORTATION

NEW N

